



ecology and environment, inc.

101 YESLER WAY, SEATTLE, WASHINGTON, 98104. TEL. 206/624-9537

International Specialists in the Environment

February 1, 1989

Mr. Floyd W. Zumwalt
(b) (6)
Albany, Oregon 97321

Dear Mr. Zumwalt:

Per Keith Stubb's conversation with Karl Morgenstern of our office on January 31, 1989, this letter is to confirm our visit to Magnum Salvage/Horizon Vehicles, located at 1052 Goldfish Farm Road, Albany, Oregon, on February 7, 1989, at 1300 hours.

Magnum Salvage has been identified by the United States Environmental Protection Agency (EPA) Region X and Oregon Department of Environmental Quality (ODEQ) from preliminary assessment screening as requiring additional information to accurately profile the nature and extent of past waste disposal activity at the site.

The EPA has been given authority under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) of 1980, as amended by the Superfund Amendments and Reauthorization Act (SARA) of 1986 (42 U.S.C. § 6901 et seq.; Sec. 104), to gain access to sites where hazardous substances may have been generated, stored, treated, disposed, or transported. Ecology and Environment, Inc. (E & E) is an authorized contractor of EPA (Contract No. 68-01-7347) (CERCLA; Sec. 115) and is acting on their behalf as field investigators.

A site inspection is performed to determine the impact or potential impact on the environment of any hazardous substances which may exist in an uncontrolled manner at your facility. A site inspection is subsequently reflected in a report (EPA Form #2070-13), a copy of which is enclosed for your information. The site inspection report provides a basis for determining if any further action is required at the site.

A checklist is also provided. The inspection process can be expedited if you will provide the information outlined in the checklist.

You may assert a claim of confidentiality for any information entitled to protection under 40 CFR, Part 2, Subpart B by designating data you believe is entitled to such protection and submitting that data separately.



Mr. Floyd W. Zumwalt
Magnum Salvage/Horizon Vehicles
Page 2

I expect that a representative of the ODEQ will participate in the inspection. If you have any questions regarding our site visit, please contact Karl Morgenstern or me at (206) 624-9537. Please contact William Glasser, USEPA, at (206) 442-7215 if you have questions regarding the purpose for this inspection.

Sincerely yours,

A handwritten signature in cursive script, reading "Jeffrey Villnow", followed by a horizontal line extending to the right.

Jeffrey Villnow
Field Investigation Team Manager

JV:taa

Enclosures

CC: William Glasser, HWD-SM, USEPA, Region X
John Osborn, ESD-PO, USEPA, Region X
Karl Morgenstern, E & E, Seattle